

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

FN823
NW
> 1
1.132 mi.
5975 ft.

CONSTRUCTION SITE
1824 SHORE PARKWAY
BROOKLYN, NY

NY Spills S117973744
N/A

Site 2 of 8 in cluster FN

Relative:
Higher

Actual:
8 ft.

SPILLS:

Name: CONSTRUCTION SITE
Address: 1824 SHORE PARKWAY
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1502100 / 2015-06-02
Facility ID: 1502100
Facility Type: ER
DER Facility ID: 162113
Site ID: 508349
DEC Region: 2
Spill Cause: Human Error
Spill Class: C4
SWIS: 2401
Spill Date: 2015-05-27
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 2015-05-27

CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2015-05-27
Spill Record Last Update: 2015-06-02
Spiller Name: STEVE COLVIN
Spiller Company: SOIL SOLUTIONS
Spiller Address: 1824 SHORE PARKWAY
Spiller Company: 999
Contact Name: STEVE COLVIN
DEC Memo: "5/27/15 TJD Spoke with Steve at Soil Solutions. Construction vehicle backed into a bucket of hydraulic oil knocking it over - spilling a few ounces of hydraulic oil to soil. Product and impacted soil - estimated as 1/2 garbage bag (20 lbs)- was recovered and disposed of with construction waste. No further action is required. Spill closed."
Not reported
Remarks: "clean up complete"

All Materials:

Site ID: 508349
Operable Unit ID: 1257661
Operable Unit: 01
Material ID: 2260688
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .05
Units: G
Recovered: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Oxygenate:

Not reported